

Softspa Sentinel

March 2009

Volume 21, Issue 1

Nationwide Softspas, Inc. 157 Valley View Dr. Craig, Colorado 81625
970-824-3956 303-589-4646 800-779-3956
www.nationwidesoftspas.com

Helping You Relieve Stress



Keep your softspa like new :

- * Keep available bromine/chlorine low (1-2 ppm) to gather bacteria.
- * Add **Softrise** to keep ph up to 7.8 ppm and alkalinity up to 120 ppm.
- * Add **Softshock**, weekly, to oxidize out Br./chlor. holding bacteria.
- * Add **Spa Perfect** to oxidize out body oils and aid in filter cleaning.
- * Use **Renew** to clean filter bi-monthly and wipe hair/lint from suction cover.
- * Remove sand/debree from bottom of softspa with **Grit Gitter** or **Spa Vac**.
- * Replace pump seals approx. every 2 years to prevent motor damage.
- * Replace (inside/outside vinyl) liner if it becomes wrinkled and brittle.
- * Replace worn out thermal cover if it no longer holds in heat.
- * Replace circuit board or relay if controls malfunction.

Buy now to beat price increase

Order before March 20, 2009

- * 15% off current **Essentials** prices with **FREE** delivery on \$100. + orders.
- * ST-230 @ \$2195. & ST-315 @ \$2895 with **FREE SHIPPING**.
- * Only 2.9% sales tax in Colorado and **NO** sales tax outside Colorado.



We are here to serve you by helping you keep your softspa in good operating order. This starts with supplying you with the proper water treatment products formulated for our vinyl lined softspas and informing you of their proper use to prevent unnecessary wear to the liners , o-rings and seals.

Bromine or chlorine needs to be kept down to 1-2 ppm, alkalinity up to 120 and ph up to 7.6. Keeping these reading will help keep your liner pliable and help your pump seals last approximately 2 years. Be sure to check for a pump seal leak and have us replace them at the first sign of leaking to prevent further damage to the impeller, motor and controls.

Something as simple as cleaning the filter every 2 weeks and the suction cover after each use can prevent pre-mature motor 'burn-out' due to the pump having to work harder. Even a single hair trapped in the pump seals can cause it to malfunction and leak pre-maturely.

If your liner becomes wrinkled and brittle, we can ship you a new one and help you change it, yourself, with instruction over the phone or our instructional video. Your worn thermal cover can be replaced with the latest custom or standard bi-fold cover.

As with your automobile, there comes a time when it makes more sense to replace rather than repair your softspa. We can help with either a reconditioned pre-owned trade-in softspa or a new, vastly improved, Softub.

Product

Now through February 20, 2005 we are offering you '*Essentials*' products at **15%off with free shipping** on orders over \$50.00. Plus we have specially priced **the new, improved, Softubs at \$ 2,495. (T-140), \$3,195. (T-220) and \$3,695. (T-300) plus freight.** That's a **\$500.00 savings** on the newest models of the world's most popular

Product Specials

one you reter buys a new Softub from us. Be sure to call or e-mail us with any questions or concerns and let us know what we can do to KEEP you in hot water.